

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




Figure 1A





Figure 1B



## Coniferous Wood Anatomy

soft woods

tracheids

pit pairs

ray cells

resin canal


Figure 2



## Bordered Pit

cell wall      torus      pit aspiration  
pit aperture      margo (microfibrils)      simple pits

Figure 3




Cross section of  
micronized copper  
hydroxide treated  
wood sprayed with  
copper indicator



Cross section of  
untreated wood  
sprayed with copper  
indicator

Figure 4A



**Figure 4B**



Figure 5